



# Preparation for OEM-1

Activities for CI Co-ordinators and CI Production & Maintenance Champions

## Edition 8

Operator Equipment Management Step 1 is the start of the 7 step journey to achieving Zero Breakdowns, Zero Quality Problems and Zero Accidents or Incidents.

Typically a 2-3 year structured development process involving 10-12 cycles of education, demonstration, doing and reflection so as to achieve set outcomes.

Each cycle spans 2-4 months commencing with a half-day kick-off workshop and concluding with a team presentation.

Mid-way through the cycle the team puts forward its improvement plan to allow the Leadership Team to review progress and, if necessary, adjust the boundaries to ensure the team will be successful.

The Operator Equipment Management 7 Step process is supported throughout by People & Leadership Development activities.

### **Suggested Pre-reading:**

### **Preparation for Area Based Teams & Work Area Management**

# Contents

	<b>Page</b>
<b>1.0 Background</b>	<b>3</b>
1.1 Purpose of Work Area Management	3
1.2 Review of the Key Learning's from WAM Cycle	3
1.3 Key Roles & Responsibilities of Area Based Teams & Operators	5
<b>2.0 Overview of OEM Activities</b>	<b>6</b>
2.1 Outline of Operator Equipment Management	6
2.2 The 4 Stages of Operator Equipment Management	7
2.3 The 7 Steps of Operator Equipment Management	8
2.4 Details of OEM Activities	9
<b>3.0 Preparation for OEM-1</b>	<b>11</b>
3.1 Review your WAM Improvement Areas for extending to OEM Activities	11
3.2 Review Base Skills of Area Based Teams	11
3.3 Review Team Skills of Area Based Teams	11
3.4 Review Allocated Support for the Area Based Teams	12
3.5 Establish Time for Formal Improvement Activities for the OEM-1 Cycle	12
3.6 Establish Area Based Team Mandate for OEM-1 Cycle	13
3.7 Establish Team Boundaries for OEM-1	13
3.8 Establish Meeting and Activity Plan for OEM-1	14
3.9 OEM-1 Team Information Sheets	15
3.10 Prepare CI Champion presentation for the OEM-1 Kick-off	15
3.11 Review Steps to be covered in OEM-1 Kick-off Workshop	16
3.12 Prepare Training Aides for OEM-1 Kick-Off Workshop	16
3.13 Determine OEM-1 Schedule	17
3.14 Prepare Sheets for OEM-1 Noticeboard and Scoreboard	17
3.15 Maintenance preparation for OEM-1	18
3.16 Establish Defect Tagging System	18
3.17 Order Supplies for OEM-1 cycle	23
3.18 Brief Team Leader for OEM-1 cycle	23
<b>4.0 Required Outputs</b>	<b>24</b>

For further information about TPM & Lean, CI, Operational Risk Minimisation, or the 5 Level Milestone Excellence Award, please contact **Ross Kennedy** – President, CTPM on +61 2 4226 6184 or email him on [ross.kennedy@ctpm.org.au](mailto:ross.kennedy@ctpm.org.au), or visit the CTPM web page at [www.ctpm.org.au](http://www.ctpm.org.au)