



# Preparation for OEM-3

**Activities for TPM<sup>3</sup> Co-ordinator, Maintenance Department, Production Department and HR / Training Department**

## **Edition 7**

Operator Equipment Management Step 3 (OEM-3) is the first step where we embark on formally teaching Operators about their equipment. OEM-3 focuses on Lubrication and is the fore-runner to Operator Equipment Management Step 4 where we expand the training to a series of modules covering the various functions of the equipment they operate.

Prior to commencing OEM-3 we suggest a Micro Maintenance Improvement Team – Lubrication is established to rationalise and standardise lubrication followed by a Micro Education & Training Lubrication Skills Team to map out the lubrication training requirements and methods to deliver the training.

# Contents

	<b>Page</b>
<b>1.0 Background</b>	<b>3</b>
1.1 Purpose of Work Area Management	3
1.2 Review of the Key Learning's from WAM Cycle	3
1.3 Key Roles & Responsibilities of Area Based Teams & Operators	5
<b>2.0 Overview of OEM Activities</b>	<b>6</b>
2.1 Outline of Operator Equipment Management	6
2.2 The 4 Stages of Operator Equipment Management	7
2.3 The 7 Steps of Operator Equipment Management	8
2.4 Details of OEM Activities	9
<b>3.0 Preparation for OEM-3</b>	<b>11</b>
3.1 Establish Micro Maintenance Improvement Team - Lubrication	11
3.2 Establish Micro Education & Training Lubrication Skills Team	12
3.3 Review your OEM-2 Improvement Areas for extending to OEM-3 Activities	12
3.4 Review Base Skills of Area Based Teams	12
3.5 Review Team Skills of Area Based Teams	13
3.6 Review Allocated Support for the Area Based Teams	13
3.7 Establish Time for Formal Improvement Activities for the OEM-3 Cycle	13
3.8 Establish Area Based Team Mandate for OEM-3 Cycle	14
3.9 Establish Team Boundaries for OEM-3	14
3.10 Establish Meeting and Activity Plan for OEM-3	15
3.11 OEM-3 Team Information Sheets	16
3.12 Prepare TPM <sup>3</sup> Champion presentation for the OEM-3 Kick-off	16
3.13 Review Steps to be covered in OEM-3 Kick-off Workshop	17
3.14 Prepare Training Aides for OEM-3 Kick-Off Workshop	17
3.15 Determine OEM-3 Schedule	18
3.16 Prepare Sheets for OEM-3 Noticeboard and Scoreboard	18
3.17 Order Supplies for OEM-3 cycle	19
3.18 Brief Team Leader for OEM-3 cycle	19
<b>4.0 Required Outputs</b>	<b>20</b>

For further information about TPM<sup>3</sup>, TPM & Lean, Operational Risk Minimisation, or the 5 Level Milestone TPM<sup>3</sup> Excellence Award, please contact **Ross Kennedy** – President, CTPM Australasia on +61 2 4226 6184 or email him on [ross.kennedy@ctpm.org.au](mailto:ross.kennedy@ctpm.org.au), or visit the CTPM web page at [www.ctpm.org.au](http://www.ctpm.org.au)